

Record #	Applicant Name	Street No	Street Name	Unit	Work Description
B-20-563	Justin Annis	16	SYCAMORE KN		Shed: Kloter Farms to trailer and install a 14' x 36' detached accessory storage shed on the west side of the property o Porch: Replace/Rebuild the Left side porch which has deteriorated over time.
B-20-565	Paul Davis Restoration	8	SPRING ST		Windows: 1 replacement window in the bathroom, 2 replacement Strip existing shingles and replace with asphalt shingles; Repair broke window in rear; Replace tub, toilet and sink
B-20-566	Window World	21	WASHINGTON AV		
B-20-568	Jailyn Gonzalez	16	HILLSIDE AV		Insulation: Insulate attic area's in 8" X 5" of blow cellulose.
B-20-569	TOM FEHILY	24	JEWETT LN		
B-20-570	G NICHOLAS WOHLERS	15	WOODBIDGE ST		Emergency Structural repair and foundation work to Back Corner of building. A car drove into the building causing structural dam PELLET STOVE: PELLET INSERT INTO MASONRY FIREPLACE Wood stove: Install a wood stove insert into to a masonry fireplace
B-20-572	jay peloquin	28	HIGHLAND AV		
B-20-573	STACY LAVERTU	149	N MAIN ST		Dura vent with stainless steel 6 inch liner Install class I cellulose to 1266 square feet to sided walls.
B-20-575	Robert Calhoun	7	PINE HILL RD		
B-20-576	Suzanne Couture	30	APPLEWOOD LN		Insulation: Air seal attic, add 9" open blow cellulose to attic, add ventilation chutes in attic, seal and insulate 1 attic
B-20-579	Jailyn Gonzalez	65	RIVER RD		Repair sky-light; rebuild chimney form top of roof up; replace gutters; Install new garage door; install 9 windows (4 front porch)
B-20-587	Caitlin Going	12	LEXINGTON ST		Repairs after fire damage. Repair of damaged ceiling joists in basement, repair damaged siding and sheathing on exterior
B-20-589	Jeff Marion	18	Wood Ave		New Construction: a new single-family home with approximately 1614 SF of living space with a drive-under 2-car garage.
B-20-592	Window World	145	LATHROP ST		
B-20-593	Window World	14	PROSPECT ST		Window: 1 basement hopper
B-20-594	Paul Schmidt	23	PINE ST		Window: 1 replacement window in living room
B-20-562	Jaime Morin	38	PARK AV		Insulation: 432 sq ft, interior blown cellulose Insulation
B-20-564	Gary Grout	12	JEWETT LN		Window: Replacement of 3 windows, 1 livingroom, 1 kitchen, 1 Reroof: Tearing off a portion of the roof of which was damaged by

B-20-571	EVERETT SEXTON	51	EAST ST	Reroofing: Remove and replace existing shingles on entire roof
B-20-581	David Labonte	45	Bridge Street	Reroof: Whole roof
B-20-580	David Labonte	43	BRIDGE ST	Reroof: Whole building
B-20-582	DAVE MINER	213	N MAIN ST	Reroof: front half of garage
B-20-588	DAVE MINER	7	HILLSIDE AV	Reroof: strip & reroof lifetime shingles
B-20-591	Daniel Genga	45	Bridge Street	Reroof: Property at 1-3 Grant Street. Tear off old roof, new ice/water, felt paper, drip edge and shingles
B-20-584	NICHOLAS BERNIER	26	WAITE AV	Roof: Remove existing roof covering.
B-20-585	Daniel Genga	43	BRIDGE ST	Reroof: Tear off existing, 6 ft of ice/water, felt paper, drip edge
B-20-586	Daniel Genga	45	Bridge Street	Reroof: Tear off existing, new ice/water, felt paper, drip edge and shingles